


CHANGE EFFICIENCY AS FOLLOWS	NUMBER OF POINTS	FOR NUMBER OF STAGES
RAISE	2	2
"	3	3
"	4	5

NOTE: ANY CHANGE IN EFFICIENCY AFFECTS EITHER THE HEAD OR HORSE POWER CORRESPONDINGLY.

S.C. H.P. - 75'
S.O. H.P. - 58'
WITH NO ENAMEL ON IMPELLER
LOWER EFFICIENCY 3 POINTS.



HYDRAULIC PERFORMANCE GUARANTEED AT THE DESIGNATED POINT ONLY AND IS CONTINGENT ON WELL PROPERLY FURNISHING PUMP WITH NON-AERATED OR NON- GASEOUS WATER FREE FROM AB- RASIVES. PUMP BOWLS MUST BE PROPERLY ADJUSTED FOR THE HEAD AT WHICH THEY OPERATE AND MUST BE SUBMERGED.	CURVE NO.	IMPELLER NO.	IMPELLER DIA.	TAKEN FROM	PEERLESS PUMP DIVISION FOOD MACHINERY CORPORATION LOS ANGELES 31, CALIF. 	PERFORMANCE PER STAGE	
	1	T-82170-E	12 ¹³ / ₁₆ " x 14 ¹¹ / ₁₆ "	2009		20" H	DEEP WELL
	2					1160	TURBINE PUMP
	3						R. P. M.
						SHEET NO. R-1006	

PRINTED IN U. S. A.