


BOWL T-80778



CHANGE EFFICIENCY AS FOLLOWS	NUM. O. POINTS	FOR NUMBER OF STAGES
RAISE	2	6
"	1	4
"	0	3
LOWER	2	1


NOTE: ANY CHANGE IN EFFICIENCY
AFFECTS EITHER THE HEAD OR
HORSE POWER CORRESPONDINGLY.

Section 110

TURBINE PUMPS

HYDRAULIC PERFORMANCE CONTINGENT ON WELL PROPERLY FURNISHING PUMP WITH THE AMOUNT OF NON-AERATED OR NON-GASEOUS WATER FREE FROM DETRITUS AT ANY HEAD ON THIS CURVE.	CURVE NO.	IMPELLER NO.	IMPELLER DIA.	TAKEN FROM	PEERLESS PUMP DIVISION FOOD MACHINERY CORPORATION LOS ANGELES 31, CALIF. 	PERFORMANCE PER STAGE	
	1	T80727	11½	T357		16 M	DEEP WELL
	2	T80727	11⅛	T349		1760	TURBINE PUMP
	3						R. P. M.
						SHEET NO.	R-426

BOWL-T-80778



TURBINE PUMPS

Section 110

HYDRAULIC PERFORMANCE CONTINGENT ON WELL PROPERLY FURNISHING PUMP WITH THE AMOUNT OF NON-AERATED OR NON-GASEOUS WATER FREE FROM DETRITUS AT ANY HEAD ON THIS CURVE.	CURVE NO.	IMPELLER NO.	IMPELLER DIA.	TAKEN FROM	PEERLESS PUMP DIVISION FOOD MACHINERY CORPORATION LOS ANGELES 31, CALIF. 	PERFORMANCE PER STAGE	
	1	T80727	10 ⁵ / ₈	T351		16M	DEEP WELL TURBINE PUMP
	2	T80727	10 ¹ / ₄	T366		1760	R. P. M.
	3					SHEET NO.	R427