




A Sterling Company

VERTICAL TURBINE PUMPS

Section 140
9-88



HYDRAULIC PERFORMANCE WARRANTY	CURVE NO.	IMPELLER NO.	IMPELLER DIA.	TAKEN FROM	Customer _____		
	1	4601873	6.23x8.06	61298	Item _____		
	2	4601873	5.88x7.84	61306	Peerless Ref. No: _____		
	3	4601873	5.56x7.63	61333	Laboratory Performance		
	4	4601873	5.25x7.44	61360	SIZE 10HHA	RPM 1770	CURVE 4806377

PUMP DESCRIPTION: Driver _____; Head _____; Column _____

GUARANTEED BOWL ☐ PERFORMANCE: Capacity _____ gpm; Head _____ ft; Eff _____ %; BHP _____

FIELD ☐